

1.5.1 Asset Register Bus Shelter Condition Report Example



Bridgend Town Council
Bus Shelter Survey

Date	25.03.2021
Officer	K Davies

Full Asset Ref	Ward	Location	Address 1	Location description	Grid Ref
BTC.012-BS.11	Oldcastle	opp Priory Avenue jct	Ewenny Road	Opp junction Priory Ave	9060 7842
Construction Type		Penybont Stone			
Map				Image	

Condition

Stone built with "ceiling". Appears sound. Warped & split wooden panel to front fascia. Some rot to rear wooden panel corner. Ceiling inside pulled away slightly. Green bench to left side of structure. Located on privately owned BCBC land (not highway) - licence to occupy 4/10/17

